

# CERTIFICATE

Ship: M/S VIKE SFE 2010

Home Port: LANDSKRONA

## FIRE EXTINGUISHERS

We hereby certify that the following equipment this day have been checked on board the M/S VIKE in Landskrona.

All units have been left in Good and Working Condition.

|   |     |        |     |                 |            |
|---|-----|--------|-----|-----------------|------------|
| 4 | pcs | PRESTO | PG6 | Dry Powder      | type 6 kgs |
| 2 | pcs | PRESTO | K5  | CO <sub>2</sub> | type 5 kgs |

Next service 2021-12

Gothenburg 2020-12-07



**Presto Brandsäkerhet AB**

Patric Liljedahl



## Inspection of Fire Extinguishing Equipment

|   |                 |   |                             |   |                 |                              |
|---|-----------------|---|-----------------------------|---|-----------------|------------------------------|
| Year:<br><b>20</b>                                      | Month:<br>12    | Day:<br>07  | Name of vessel:<br>M/S VIKE | Imo:                                      |                 |                              |
| Call sign:<br>SFE2010                                   |                 |   | Home port:<br>Landskrona    | Place of service:<br>Landskrona           |                 |                              |
| E-mail/Phone nr:<br>info@landskronabaten.se 0706-788300 |                 |   |                             | Classification:                           |                 |                              |
| <b>Description of type</b>                              |                 | <b>Description of working codes (Performed/Recommended)</b> |                             |   |                 |                              |
| DP  | Dry powder      | 1 = Inspected   |                             | 6 = New extinguisher                      |                 |                              |
| W   | Water           | 2 = Recharged (agent & propellant gas)                      |                             | 7 = New bracket (Extinguisher)            |                 |                              |
| F   | Foam            | 3 = Hydrostatically tested                                  |                             | 8 = Rejected                              |                 |                              |
| CO <sub>2</sub>   | Carbon Dioxide  | 4 = Repaired  |                             | * = Last hydrostatically test or recharge |                 |                              |
|   |                 | 5 = Repainted   |                             |   |                 |                              |
| <b>Qto/No</b>   | <b>Location</b> | <b>Make/Model</b>   | <b>Type</b>                 | <b>Year/month*</b>                        | <b>Capacity</b> | <b>Performed/Recommended</b> |
| 1   | Deck            | Presto K5   | Co2                         | 2018                                      | 5kg.            | 1                            |
| 2   | Deck            | Presto PG6  | DP                          | 2018                                      | 6kg.            | 1                            |
| 3   | Deck            | Presto PG6  | DP                          | 2018                                      | 6kg.            | 1                            |
| 4   | Engine          | Presto PG6  | DP                          | 2018                                      | 6kg.            | 1                            |
| 5   | Engine          | Presto K5   | Co2                         | 2018                                      | 5kg.            | 1                            |
| 6   | Spare           | Presto PG6  | DP                          | 2018                                      | 6kg.            | 1                            |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
|   |                 |   |                             |   |                 |                              |
| Note:   |                 |   |                             |   |                 |                              |

201207 Lars Anlander

Inspection performed by (Date &amp; signature)